




## SKL100 • SKL150 • SKL200 • SKL600 THE SECURITY KWIK-LOC™ SELF LOCKING CABLE JOINER Assembly Instructions and Warnings




Unscrew the locking nut and set screw until the release pin is pushed back fully. Pull release pin back and pass wire through Security Kwik-Loc. Failure to pull adjustment pin first may cause damage to serrated teeth and reduce holding capacity.




Loop wire through anchor.




Pull adjustment pin back and pass wire back through Security Kwik-Loc. Push through at least 6" of wire rope.



Always confirm engagement of Security Kwik-Loc on wire before applying load by pushing the adjustment pin in the opposite direction of the arrows on the cable lock and then pulling the cable also in the opposite direction of the arrows on the cable lock.



To adjust, take the load off and pull the tail slightly to disengage teeth, then release using adjustment pin.



Tighten the locking nut and bolt until the release pin can no longer be moved.

SECURITY KWIK-LOC	Cable Diameter	Construction	Material	Safe Working Load Range at 5:1 Safety Factor
SKL100	RWC3	7 x 7	Galvanized Steel*	25-150 lbs. (12-100 kg)
SKL150	RWC4	7 x 7	Galvanized Steel*	25-250 lbs. (12-114 kg)
SKL200	RWC6	7 x 19	Galvanized Steel*	50-640 lbs. (25-180 kg)
SKL600	RWC8	7 x 19	Galvanized Steel*	50-1,100 lbs. (25-500 kg)



# SECURITY KWIK-LOC™ SELF LOCKING CABLE JOINER

## Manufacturer's Recommendations

### Recomendaciones del fabricante

**ALWAYS FOLLOW THE INSTALLATION INSTRUCTIONS BELOW.** There are many variables to be considered when installing Rize cables and affixing them to upper attachments. The contractor is solely responsible for selecting the appropriate Rize product for the specific circumstances of each installation. The contractor must select the appropriate Rize product that meets the approval of the mechanical engineer and complies with all applicable codes and job specifications.

- To ensure hanging system integrity and safety, use only RIZE cable
- Always pull adjustment pin back before passing wire rope through RIZE cable lock. Failure to pull adjustment pin first may cause damage to serrated teeth and reduce holding capacity.
- Always confirm engagement of KWIK-LOC on wire before applying load by pushing the adjustment pin in the opposite direction of the arrows on the cable lock and then pulling the cable also in the opposite direction of the arrows on the cable lock.
- Do not use for loads outside the stated range of the product
- Do not exceed the safe working range of the product
- Remove damaged cable end prior to inserting into the KWIK-LOC
- Do not use on coated wire rope
- Spray painting of the Rize Suspension Hanging System after installation is acceptable, at the installing contractor's discretion, if the installing contractor physically confirms engagement of each cable lock on the cable prior to and after painting, and in strict accordance with the Rize Installation Instructions. Brush painting is not acceptable. Do not paint Cable or Cable Lock prior to installation. Do not reposition Cable Lock after painting.
- Do not apply lubricant
- Do not use for lifting or dynamic loads
- Keep the product clean and free from dirt
- Do not use in chlorinated atmospheres
- For use on static load applications only

Scan for instructions

Escanear para obtener instrucciones



## FOR DRY LOCATIONS ONLY

**USE ONLY WITH RIZE CABLE.**

**SIGA SIEMPRE LAS SIGUIENTES INSTRUCCIONES DE INSTALACIÓN.** Hay muchas variables que deben tenerse en cuenta al instalar los cables Rize y fijarlos andajes superiores. El contratista es el único responsable de seleccionar el producto Rize adecuado para las circunstancias específicas de cada instalación. El contratista debe seleccionar el producto Rize adecuado que cumpla con la aprobación del ingeniero mecánico y cumpla con todos los códigos y especificaciones de trabajo aplicables.

- Para asegurar la integridad y seguridad utilice únicamente cables de RIZE
- Pasador de ajuste, siempre tirar la pestaña hacia atrás antes de pasar el cable por el cable lock de RIZE. No tirar pasador de ajuste primero, puede causar daños en dientes de sierra y reducir capacidad de retención.
- Siempre confirmar la activación del KWIK-LOC en el cable antes de aplicar carga empujando el pasador de ajuste en la dirección opuesta a la de las flechas en el cable lock y a continuación, tirando el cable también en la dirección opuesta a la de las flechas en el bloque de el cable lock.
- Respete la carga máxima especificada en el dispositivo
- Por motivos de seguridad tenga especial cuidado en no sobrepasar el rango de la carga útil de tensor
- Corte los extremos deshinchados del cable antes de pasarlo el KWIK-LOC
- La aplicación de pintura u otro tipo de revestimiento puede bloquear el dispositivo
- La pintura en aerosol del sistema de suspensión de Rize después de la instalación es aceptable, a discreción del contratista de instalación, si el contratista de instalación confirma físicamente la conexión de cada bloque de cable en el cable antes y después de pintar, y en estricto cumplimiento con las Instrucciones de instalación de Rize. No es aceptable pintar con brocha. No pinte el cable o el candado de cable antes de la instalación. No vuelva a colocar el bloque de cable después de pintar.
- Evite el uso de lubricantes
- Nunca debe utilizar el tensor para levantar cargas
- Mantenga el producto limpio y exento de polvo
- No utilizarlo en atmósferas con cloro
- Para uso solo en aplicaciones de carga estática



## •SOLO PARA AMBIENTES SECOS USAR CABLES DE RIZE SOLAMENTE.

The products are provided on an "as is" basis; There shall be no express or implied warranty, including without limitation, warranty of merchantability or fitness for a particular purpose. Supplier shall not under any circumstances, be liable for indirect, special or consequential damages or lost profits. Los productos se comercializan tal y como se presentan; No existe una garantía expresa o implícita, incluyendo entre otras, una garantía de comerciabilidad o compatibilidad para un propósito específico. El proveedor no será responsable en ningún caso de los posibles daños indirectos, especiales o consecuencias así como de la pérdida de beneficios.

**DO NOT EXCEED THE SAFE WORKING LOAD RANGE OF THE PRODUCT**  
**NO SOBREPASE EL RANGO DE LA CARGA DE ÚTIL DEL TENSOR**